
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-288	Smoke	9/9/2009	ADS/TM	S09II1018MH	Dry	Yes	861.74

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S09II1018G1	S09II1018MH	S11II1030MH	306.281	18
S09II1007G1	S09II1007MH	S09II1018MH	421.029	12
S09II1009G1	S09II1009MH	S09II1018MH	134.431	18

Observations & Photos

Obs_ID S1028-288-OB01

Address 4601 Reisterstown Rd

Status Public

Source Sanitary Manhole

Location Yard - front

Nearest MH S11II1030MH

Comments Smoke from sanitary manhole in front yard.
4601 Reisterstown Rd.



Picture \S1028-288-OB01-P01.jpg

Comments Front yard, 4601 Reisterstown Rd.

Obs_ID S1028-288-OB02

Address 4629 Reisterstown Rd

Status Private

Source Cleanout

Location Yard - front

Nearest MH S09II1018MH

Comments Smoke from cleanout in front yard. 4629
Reisterstown Rd.



Picture \S1028-288-OB02-P01.jpg

Comments Front of house, 4629
Reisterstown Rd.